

Council Notice Boards

Walderslade

Woodbury Road junction with Tunbury Avenue

Type - Single

Condition – Good

Action – Requires some staining which can be done internally or through small contractor during winter months

Replacement Cost – Single - Man Made Timber or Wood - £890 Aluminium - £1240 Plus installation costs of £500 approximately Total - £1490 -£1740. Double - Man Made Timber or Wood - £1350 Aluminium - £1530 Plus installation costs of £500 approximately Total - £1850 -£2030

Comments – This notice board is in a good condition and only requires some minor maintenance work.

Tunbury Community Hall (Metal Design)

Type - Double

Condition – Good but Perspex glazing is very dirty and requires cleaning or replacement

Action – Minor works

Replacement Cost – Single - Man Made Timber or Wood - £890 Aluminium - £1240 Plus installation costs of £500 approximately Total - £1490 -£1740. Double - Man Made Timber or Wood - £1350 Aluminium - £1530 Plus installation costs of £500 approximately Total - £1850 -£2030

Comments – This notice board is in a good condition though the Perspex will need cleaning and possible replacement. This notice board is required at this location

Victoria Road junction with York Avenue

Type - Single

Condition – Removed 4/5 years ago as it was damaged and likely to fall down.

Action – None

Replacement Cost – Single - Man Made Timber or Wood - £890 Aluminium - £1240 Plus installation costs of £500 approximately Total - £1490 -£1740. Double - Man Made Timber or Wood - £1350 Aluminium - £1530 Plus installation costs of £500 approximately Total - £1850 -£2030

Comments – This notice board has not been in place for 4 to 5 years and in that time no one has mentioned that it was no longer there. On this basis it would seem that it has not been missed. If Members wish to reinstate it, it will probably be necessary to seek the permission from the Highway Authority to replace it as it has been 4/5 years since it had to be removed because it was potentially dangerous as it was likely to fall down.

Robin Hood Lane (Lower) junction with Public Footpath

Type - Single

Condition – Poor no Perspex glazing and the door is broken. Wood is in very poor condition. It will need replacing or should be removed

Action – Replace or remove

Replacement Cost – Single - Man Made Timber or Wood - £890 Aluminium - £1240 Plus installation costs of £500 approximately Total - £1490 -£1740. Double - Man Made Timber or Wood - £1350 Aluminium - £1530 Plus installation costs of £500 approximately Total - £1850 -£2030

Comments – It is not feasible to refurbish this notice board without significant expenditure and would not prolong the life of this board to any great extent. Members will need to make a decision as to whether they wish to replace this notice board or to remove it.

Hallsfield Road junction with Hallsfield Road (Spur)

Type - Double

Condition – Poor with the doors and locks broken. It is not possible to refurbish this notice board.

Action – Replace or remove

Replacement Cost – Single - Man Made Timber or Wood - £890 Aluminium - £1240 Plus installation costs of £500 approximately Total - £1490 -£1740. Double - Man Made Timber or Wood - £1350 Aluminium - £1530 Plus installation costs of £500 approximately Total - £1850 -£2030

Comments – It is not feasible to refurbish this notice board without significant expenditure and would not prolong the life of this board to any great extent. Members will need to make a decision as to whether they wish to replace this notice board or to remove it. However, this Notice board is in an area with little footfall as it is in a side road off Hallsfield Road that does not go anywhere of any significance thereby few people pass it.

Benches

Tunbury Recreation Ground

2 Plastic Benches – in reasonable condition

2 Wooden Benches – in reasonable condition

1 Wooden Picnic Table – in reasonable condition

Action – Wooden Benches and picnic table will require staining which can be done internally or through small contractor during winter months

Blue Bell Hill

Robin Hood Lane junction with Maidstone Road

Type - Single

Condition – Very poor condition with broken locks, doors and loose legs. It is not possible to refurbish this notice board.

Action – Replace or remove

Replacement Cost – Single - Man Made Timber or Wood - £890 Aluminium - £1240 Plus installation costs of £500 approximately Total - £1490 -£1740. Double - Man Made Timber or Wood - £1350 Aluminium - £1530 Plus installation costs of £500 approximately Total - £1850 -£2030

Comments – It is not feasible to refurbish this notice board without significant expenditure and would not prolong the life of this board to any great extent. Members will need to make a decision as to whether they wish to replace this notice board or to remove it. This is the only notice board in Blue Bell Hill Village.

Benches and Map Board

Podkin Meadow

Map Board - in reasonable condition

1 Plastic Bench – in good condition

5 Wooden Benches – in reasonable condition

Action – Map Board, wooden benches and trim trail will require staining which can be done internally or through small contractor during winter months.

Robin Hood Lane

1 wooden bench – in poor condition with loose legs. This bench will either need to be replaced or removed. An approximate cost of replacement would be £500 plus installation costs of approximately £500 a total cost of £1000. Councillor Smith will not be at the meeting but has indicated that he sees no reason to retain this bench.

Eccles

Bull Lane Recreation Ground

Type - Single

Condition - Very poor condition with broken locks, doors and loose legs. It is not possible to refurbish this notice board.

Action – Replace or remove

Replacement Cost – Single - Man Made Timber or Wood - £890 Aluminium - £1240 Plus installation costs of £500 approximately Total - £1490 -£1740. Double - Man Made Timber or Wood - £1350 Aluminium - £1530 Plus installation costs of £500 approximately Total - £1850 -£2030

Comments – It is not feasible to refurbish this notice board without significant expenditure and would not prolong the life of this board to any great extent. Members will need to make a decision as to whether they wish to replace this notice board or to remove it.

Varnes Street outside Shop

Type – A Frame Board

Condition - in reasonable condition and still in use

Action – Retain and clean board

Replacement Cost – New A Frame Board - £90 approximately

Comments – Retain in use.

Benches and Map Board

Eccles Recreation Ground

Map Board - in reasonable condition

3 Plastic Bench – in reasonable condition

3 Plastic Picnic Tables – in reasonable condition

5 Wooden Benches – in reasonable condition

2 Wooden Picnic Tables – in reasonable condition

1 Metal Bench – in reasonable condition

Action – Map Board and wooden benches will require staining which can be done internally or through small contractor during winter months

Aylesford North

High Street outside Shop

Type – A Frame Board

Condition - In poor condition as regularly damaged by being kicked over

Action – Replace or remove

Replacement Cost – New A Frame Board - £90 approximately.

Comments – Currently would need to be replaced. The current shop owner has problems with it being kicked over and therefore it is not used.

Old Bridge Gardens

Type - Double

Condition - Very poor condition with broken locks, doors and loose legs. It is not possible to refurbish this notice board.

Action – Replace or remove Refurbish

Replacement Cost – Single - Man Made Timber or Wood - £890 Aluminium - £1240 Plus installation costs of £500 approximately Total - £1490 -£1740. Double - Man Made Timber or Wood - £1350 Aluminium - £1530 Plus installation costs of £500 approximately Total - £1850 -£2030

Comments – It is not feasible to refurbish this notice board without significant expenditure and would not prolong the life of this board to any great extent. Members will need to make a decision as to whether they wish to replace this notice board or to remove it. It is the main notice board in the village and Aylesford North ward.

Benches and Map Board

Forstal Road Recreation Ground

5 Wooden Benches

Action – Wooden Benches will require staining which can be done internally or through small contractor during winter months

Old Bridge Gardens

Map Board – in poor condition and Map no longer legible

1 Wooden Bench

1 Plastic Bench

Action – Wooden Benches will require staining which can be done internally or through small contractor during winter months. Map Board will also require rubbing down and staining and new map put in place

Aylesford South

Aylesford Cemetery (Metal Design)

Type - Single

Condition - Good condition

Action – None

Replacement Cost – Single - Man Made Timber or Wood - £890 Aluminium - £1240 Plus installation costs of £500 approximately Total - £1490 -£1740. Double - Man Made Timber or Wood - £1350 Aluminium - £1530 Plus installation costs of £500 approximately Total - £1850 -£2030

Comments – This notice board is aluminium and is in a good condition. Retain

Premier Parade of Shops, The Avenue

Type - Double

Condition - Poor with the doors, perspex and locks broken. It is not possible to refurbish this notice board.

Action – Replace or remove

Replacement Cost – Single - Man Made Timber or Wood - £890 Aluminium - £1240 Plus installation costs of £500 approximately Total - £1490 -£1740. Double - Man Made Timber or Wood - £1350 Aluminium - £1530 Plus installation costs of £500 approximately Total - £1850 -£2030

Comments – It is not feasible to refurbish this notice board without significant expenditure and would not prolong the life of this board to any great extent. Members will need to make a decision as to whether they wish to replace this notice board or to remove it. This is an important notice board directly opposite the shops.

A20 London Road junction with Teapot Lane

Type - Double

Condition - Poor with the doors and locks broken. It is not possible to refurbish this notice board.

Action – Replace or remove

Replacement Cost – Single - Man Made Timber or Wood - £890 Aluminium - £1240 Plus installation costs of £500 approximately Total - £1490 -£1740. Double - Man Made Timber or Wood - £1350 Aluminium - £1530 Plus installation costs of £500 approximately Total - £1850 -£2030

Comments – It is not feasible to refurbish this notice board without significant expenditure and would not prolong the life of this board to any great extent. Members will need to make a decision as to whether they wish to replace this notice board or to remove it.

Royal British Legion, Admiral Moore Drive (Metal Design)

Type - Single

Condition - Good but Perspex glazing is very dirty and requires cleaning or replacement

Action – Minor works

Replacement Cost – Single - Man Made Timber or Wood - £890 Aluminium - £1240 Plus installation costs of £500 approximately Total - £1490 -£1740. Double - Man Made Timber or Wood - £1350 Aluminium - £1530 Plus installation costs of £500 approximately Total - £1850 -£2030

Comments – This notice board is in a good condition though the Perspex will need cleaning and possible replacement. Retain

Benches

Cemetery

3 wooden benches – in reasonable condition

Action – Wooden Benches will require staining which can be done internally or through small contractor during winter months

Ferryfield

5 Wooden Benches – in reasonable condition

Action – Wooden Benches and Fitness Trail will require staining which can be done internally or through small contractor during winter months

The Hollow

2 Wooden Benches – in reasonable condition

Action – Wooden Benches will require staining which can be done internally or through small contractor during winter months